

Ersatzteilpaket Schrauben

	QUICK 2938	Bestell- Nr.
für Rändelrad	€	
8,9 x 2,5 x 4	79,30	...4401
14,5 x 3 x 5	88,30	...4403
21,5 x 5 x 8	89,00	...4405
15 x 6 x 6A11	96,10	...4439
20 x 8 x 6A13	88,30	...4441
	(W271)	

CNC



Ersatzteilpaket Backen

	QUICK 2938	Bestell- Nr.
Werkzeug	€	
F791	628,00	...4407
F792	688,00	...4409
C693	742,50	...4411
	(W271)	

CNC



Langdreh-Adapter

für Schaft mm	Werkzeug	QUICK 2938	Bestell- Nr.
16 x 16	C612	67,70	...4413
12 x 12	C612	67,70	...4415
10 x 10	C612	67,70	...4417
16 x 16	C611	67,70	...4419
12 x 12	C611	67,70	...4421
10 x 10	C611	67,70	...4423
		(W271)	


CNC



Kühlmitteldüse

für Rändelrad	Werkzeug	QUICK 2938	Bestell- Nr.
14,5 x 3 x 5	C611, C612	147,50	...4425
21,5 x 5 x 8	C611, C612	153,00	...4427
		(W271)	

CNC



Schaft für C693, F791 und F792

Schaft-Ø mm	Bohrung-Ø mm	Länge mm	QUICK 2938	Bestell- Nr.
15	9	50	283,00	...4429
20	10	50	283,00	...4431
25	10	50	283,00	...4433
			(W271)	

CNC



Laufstift

Werkzeug	QUICK 2938	Bestell- Nr.
F711 Rändelrad 10 x 4 x 4	€	...4435
F711 Rändelrad 20 x 8 x 6	14,10	...4437
F751 Rändelrad 10/15 x 4 x 4	14,30	...4443
F791 Rändelrad 10/15 x 4 x 4	14,30	...4445
851 Rändelrad 15 x 4 x 4	3,83	...7777
830 Rändelrad 20 x 8 x 6	1,46	...4449
851 Rändelrad 20 x 8 x 6	2,91	...4451
	(W271)	

CNC

